

Test Report No. SL9

No. SL918092586832TX

Page 1 of 2

DONGGUAN SUNFIRE SPORTS CO., LTD. 4B 4TH FL ZHAOXI INDUSTRIAL PARK GATE 3, RD 11 LONGYAN, HUMEN, DONGGUAN CHINA 523920

The following sample(s) was/were submitted and identified on behalf of the client as:

Sample Description	:	ONE SAMPLE OF KNITTED 250GSM 75%POLYESTER 25% SPANDEX FABRIC IN PINK FOR SPORTS WEAR
Style No. Manufacturer Supplier Country Of Origin Country Of Destination Sample Receiving Date Test Performing Period Test Performed		L7327H SUNFIRE SUNFIRE China USA,CA,AUS, NZ, Europe, etc Jul 16, 2018 Jul 16, 2018 - Jul 19, 2018 Selected tests as requested by applicant against Client's performance standard.
	*	* * *
Test Result(s)	:	Please refer to the next page(s).
Conclusion(s) Pilling Resistance	:	#
Remark(s)	:	 M = Meet Client's Requirement F = Below Client's Requirement # = No specified requirement * = No specification provided

Signed for and on behalf of SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch

Lily Wang Account Manager



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-enDocument.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Cilent's instructions, if any. The Company's osle responsibility is to its Cilent and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only. Attention is contact as at telephone: (86-755) 8307 1443,

198 Kazhu Road, Skaineka Park Guargabue Economica Technology Development District, Guargabue, China 510663 t (86-20) 82155555 f (86-20) 82075169 www.sgsgroup.com.cn 中国・广州・经济技术开发区科学城科珠路198号 邮编: 510663 t (86-20) 82155555 f (86-20) 82075169 e sgs.china@sgs.com



Test Report

No. SL918092586832TX

Page 2 of 2

Test Result:

Requirement

/

<u>Pilling Resistance</u> (ASTM D3512/D3512M-16; After 30 min, Tumbling in random tumble pilling Tester)

As Received Rating

Remarks: Pilling Rating For pilling: 5 No pilling 4 Slight pilling 3 Moderate pilling 2 Severe pilling 1 Very severe pilling 5.0

For fuzzing: 5 No fuzzing 4 Slight fuzzing 3 Moderate fuzzing 2 Severe fuzzing 1 Very severe fuzzing

Sample Photo



*** End of Report ***



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-on-Courdinated at http://www.sgs.com/en/Terms-and-Conditions/Terms-on-Courdinated at http://www.sgs.com/en/Terms-and-Conditions/Terms-on-Courdinated at http://www.sgs.com/en/Terms-and-Conditions/Terms-on-Courdinated at http://www.sgs.com/en/Terms-and-Conditions/Terms-on-Courdinated at http://www.sgs.com/en/Terms-and-Courdinated at http://www.sgs.com/en/Term

198 Kazhz Rad Skienteh Park Guarghou Econnick Technology Development District, Guargzhou, China 510663 t (86-20) 82155555 f (86-20) 82075169 www.sgsgroup.com.cn 中国・广州・经济技术开发区科学城科珠路198号 邮编: 510663 t (86-20) 82155555 f (86-20) 82075169 e sgs.china@sgs.com